


FIG. 1






FIG. 3




FIG. 4






FIG. 5




413

change to


I-hibiting à Service No change Nochunge 415 Charge to F16.7



F16.8




F1G. 9A



F16. 9B

Please weit...
Processing is XXX camplets.

F1G. 9C



F1G. 97)

	507
User defined batch file contiguetion DOB  Inhibit file;  C:\Sample\Disable.bat	
(brinhibit file: [C:\Sample\Enable.bit]	FIG. 9E
Connecting Updating Please Wait Processing is xx8 camplele	F1G. 9G
Idle timecut value [10] minuters	F16.9F